

Featuring the *Lint Blitzer™* Blower Wheel for Maximum Performance, Zero Maintenance

The Problem:

Exhaust duct lengths beyond 25 equivalent feet* reduce air velocity, often causing:

- Increased drying time
- Increased energy use
- Increased lint build-up in ductwork

The Solution:

The Dryer Duct Booster® maintains proper exhaust velocity in duct runs up to 100 equivalent feet optimizing dryer performance.



The Dryer Duct Booster® surpasses all existing dryer duct fans with features including:

- The Lint Blitzer™ blower wheel. Unlike in-line tubeaxial fans which can clog with lint, the Lint Blitzer wheel is specially designed to repel lint while providing optimum air velocity.
- 5 year no clog, no maintenance guarantee.
- Saves energy by operating only when dryer is in use.
- Permanently lubricated motor positioned out of the air stream for maximum motor life.
- Simple installation in both vertical and horizontal ducts.





Unlike in-line tubeaxial fans, which can clog with lint and require periodic cleanings, the Dryer Duct Booster's externally located motor and Lint Blitzer blower wheel mean maximum performance with zero maintenance, backed by a 5 year quarantee.

If the Dryer Duct Booster becomes inoperable due to a lint clogged blower wheel Tjernlund Products will issue a free replacement booster fan.

Automatic actuation control features self-




PSC, permanently lubricated ball bearing motor is not exposed to heat, lint or moisture. Uses less power than a 50 watt light bulb.

Rubber isolated mounting bracket eliminates vibration transfer. Rotates 360° to accommodate any mounting orientation.



See why the Lint Blitzer[™] blower wheel has a 5 year no clog guarantee

Go to www.dryerboosters.com to see for yourself how our Dryer Duct Booster outperforms typical in-line fans in a lint build-up test.






Horizontally Mounted

Vertically Mounted

Dimensions



Specifications

Model Voltage Watts **Amps** CFM LB1 120 VAC 0.5 160 50



Available From:



TJERNLUND PRODUCTS, INC.

1601 Ninth Street White Bear Lake, MN 55110-6794 Phone: 651.426.2993 800.255.4208 Fax: 651.426.9547 Visit our web site: www.tjernlund.com